



FIRE SUPPRESSION SERVICES, INC.

3802 South 2300 East
Salt Lake City, Utah 84109

(801) 277-6464
(800) 273-6465
Fax (801) 278-2199

UTAH STATE FIRE MARSHAL NO. H-5
CONTRACTOR LICENSE NO. 92-252208-5501

AUTOMATIC FIRE SUPPRESSION SYSTEM • INSPECTION REPORT

DATE: 5/30/21

CUSTOMER: Coopers Restaurant

MANUFACTURER Ansul R-102 3 gal x 2 WET ☒ DRY ☐

ADDRESS: 554 Lewis Loop #100
Fish Haven, ID 83287

NUMBER OF FUSIBLE HEAT LINKS 500 2 450 3 360

CONTACT: Tony/Diego

TYPE OF FUEL SHUT OFF Gas/Electric

EMAIL:

TANK DT 10 CARTRIDGE DT 10 RECHGE DT HYDRO DT

LOCATION OF SYSTEM CYLINDERS away

	YES	NO	N/A
1. ALL APPLIANCES PROPERLY COVERED WITH CORRECT NOZZLES	<input checked="" type="checkbox"/>		
2. DUCT AND PLENUM COVERED WITH CORRECT NOZZLES	<input checked="" type="checkbox"/>		
3. CHECK POSITIONING OF ALL APPLIANCE NOZZLES	<input checked="" type="checkbox"/>		
4. PRESSURE GAUGE IN PROPER RANGE	<input checked="" type="checkbox"/>		
5. INSPECT CYLINDER & MOUNT	<input checked="" type="checkbox"/>		
6. OPERATE SYSTEM FROM TERMINAL LINK	<input checked="" type="checkbox"/>		
7. TEST FOR PROPER OPERATION FROM REMOTE	<input checked="" type="checkbox"/>		
8. CHECK OPERATION OF MICRO SWITCH AND ELECTRIC SHUT OFFS TO APPLIANCES	<input checked="" type="checkbox"/>		
9. CHECK OPERATION OF MICRO SWITCH TO BUILDING ALARM	<input checked="" type="checkbox"/>		
10. CHECK OPERATION OF GAS VALVE	<input checked="" type="checkbox"/>		
11. CLEAN NOZZLES	<input checked="" type="checkbox"/>		
12. PROPER NOZZLE COVERS IN PLACE	<input checked="" type="checkbox"/>		
13. REPLACED FUSIBLE HEAT LINKS	<input checked="" type="checkbox"/>		
14. PIPING & CONDUIT SECURELY BRACKETED	<input checked="" type="checkbox"/>		
15. EXHAUST FAN IN OPERATING ORDER	<input checked="" type="checkbox"/>		
16. ALL FILTERS RETURNED TO PROPER LOCATION	<input checked="" type="checkbox"/>		
17. GAS FUEL SHUT OFF IN ON POS	<input checked="" type="checkbox"/>		
18. CARTRIDGE REINSTALLED	<input checked="" type="checkbox"/>		
19. REPLACE SYSTEMS COVERS	<input checked="" type="checkbox"/>		
20. SLAVE SYSTEM IN OPERATION	<input checked="" type="checkbox"/>		
21. CLEAN CYLINDER & MOUNT	<input checked="" type="checkbox"/>		
22. IS REMOTE PULL STATION UNOBSTRUCTED	<input checked="" type="checkbox"/>		
23. PROPER HAND PORTABLE EXTINGUISHERS	<input checked="" type="checkbox"/>		
24. SERVICE TAG ON SYSTEM	<input checked="" type="checkbox"/>		
25. NON-COMPLIANCE TAG ON SYSTEM	<input checked="" type="checkbox"/>		

YOU 'SERVICED'/'INSPECTED' the system!!!!?
AND DIDN'T RED-TAG it.
Dear me Ricardo! What will Idaho AHJ's think of us?
PLEASE correct this report! to reflect what you told me.

DEFICIENCIES system missing (2) link above Fryer.
System piping is all clogged up.

ON THIS DATE, THE ABOVE SYSTEM WAS TESTED AND INSPECTED IN ACCORDANCE WITH PROCEDURES OF THE PRESENTLY ADOPTED EDITIONS OF NFPA 17, 17A, 96 AND THE MANUFACTURER'S MANUAL AND WAS OPERATED ACCORDING TO THESE PROCEDURES WITH RESULTS INDICATED ABOVE.

[Signature]
SERVICE TECHNICIAN

61884
HE #

CUSTOMER'S AUTHORIZED AGENT

THE SERVICE TECHNICIAN CERTIFIES THAT THE SYSTEM WAS PERSONALLY INSPECTED AND FOUND CONDITIONS TO BE AS INDICATED ON THIS REPORT.